

# UL Warns of Counterfeit UL Mark on Fire Doors (Release 15PN-06, 15PN-07, 15PN-08, and 15PN-09)

NORTHBROOK, Ill., May 5, 2015 — The following is a notification from UL that the fire doors identified below bear counterfeit UL Marks.

[\(Version française\)](#)

[\(Versión en español\)](#)

**NORTHBROOK, Ill., May 5, 2015** — The following is a notification from UL that the fire doors identified below bear counterfeit UL Marks. The fire doors have not been evaluated by UL to the appropriate Standards for Safety and it is unknown if these fire doors comply with any safety requirements.

**Release 15PN-06**

**Name of Product:** Fire Door, Fire Rating 90 Minutes

**Identification:** The products bear a counterfeit UL Certification Mark and the following:



<b>This Door is Certified To UL GVTV.R25971</b>
<b>Fire Rating 90 minutes</b>
<b>Changshu Fengsheng Building Decoration Wood Industry Co.Ltd</b>
<b>LINYUAN RD 2-1 ZHITANG TOWN, CHANGSHU SUZHOU, JIANGSU 215531 – CHINA</b>


The following table notes the differences between the authentic UL Label and the counterfeit UL Label:


Authentic Label	Counterfeit Label
UL Mark at top center position of label	UL Mark on left side of label
“CLASSIFIED” Notation	“LISTED” Notation
Reference To File R25970	Reference To GVTV.R25971
Fire Door Rating: 1-1/2H	Fire Door Rating “90 minutes”
Minimum Latch Throw 0.69 IN.	No reference to Minimum Latch Throw
Temp Rise: 30min-250C Max	No reference to Temperature Rise
Model No. MFM 2022 d6	No reference to Model no


**MEDIA CONTACT**


**Brooke Higginbotham**  
*Public Relations Specialist*  
 P: +1.847.664.1298  
[Brooke.Higginbotham@ul.com](mailto:Brooke.Higginbotham@ul.com)


**FEATURED**

- 

**Fighting More Than Fire: Firefighters Battling Cancer and...** [>](#)
- 

**Biosecurity Grows in Importance on Heels of Midwest...** [>](#)
- 

**UL’s Dr. Scott Harris Responds to Bird Flu...** [>](#)
- 

**UL Maintains Customers’ ‘Circle of Trust’** [>](#)
- 

**Behind the Scenes: Assessing Wearable Battery Safety** [>](#)

[see all >](#)

**RECENT PUBLIC NOTICES**

- UL Warns of Counterfeit UL Marks on Zimpex Protective Garments Used for Protection of Industrial Personnel Against Flash Fire (Release 15PN-15) [»](#)
- UL Warns of Unauthorized UL Mark on Solenoid-type Oscillating Water Pump (Release No. 15PN-05) [»](#)
- UL warns of potentially hazardous communications cables (Releases 15PN-01, 15PN-03 and 15PN-04) [»](#)
- UL and ULC Warn of Counterfeit UL and ULC Marks on a Fire Valve (Release 15PN-02) [»](#)
- UL International Demko Warns of Unauthorized ENEC-15 Mark on LED tubes (14PN-24) [»](#)

Photograph of the Counterfeit Label:

[see all >](#)



Distributor: Known to be distributed in Doha, Qatar

**Release 15PN-07**

**Name of Product:** Fire Door, Fire Rating 2 hours

**Identification:** The products bear a counterfeit UL Certification Mark and the following:

SH DOOR TECH CO. LTD
168-15 YUngtan Dong, Chungiu-Shi
Chungbuk 386-250, Republic of Korea,
SWINGING TYPE FIRE DOOR
FIRE RATING – 2 HOURS
CONFORMS TO UL10 B, 10 <sup>TH</sup> Edition.



The following table notes the differences between the authentic UL Label and the counterfeit UL Label:

Authentic Label	Counterfeit Label
UL Mark on the left side of the label	UL Mark on the right side of the label
“CLASSIFIED” Notation	No “CLASSIFIED” Notation
UL Label part no. 10-3-4-S0045 noted at top	No label part no. noted
No reference to UL Standard	“CONFORMS” TO UL 10B, 10 <sup>TH</sup> EDITION

Photograph of the Counterfeit Label:



**Distributed:** Known to be distributed in Bangladesh

**Release 15PN-08**

**Name of Product:** Swinging Type Fire Door, Fire Rating 1.5 HR

**Identification:** The products bear a counterfeit UL Certification Mark and the following:



10-3-4-50045	MINIMUM
SWINGING TYPE FIRE DOOR	LATCH
FIRE RATING 1.5 HR.	THROW
NO. P5661023	84X48" INCH

The doors contain no other identifying features or nameplate markings.

**Photograph of the Counterfeit Label:**



**Distributed:** Known to be distributed in Bangladesh

**Release 15PN-09**

**Name of Product:** Swinging Type Fire Door, Fire Rating 1.5 HR

**Identification:** The products bear a counterfeit UL Certification Mark and the following:



10-3-4-50045	MINIMUM
--------------	---------

SWINGING TYPE FIRE DOOR	LATCH
FIRE RATING 1.5 HR.	THROW
NO. P566969	44X36" INCH

The doors contain no other identifying features or nameplate markings.

**Photograph of the Counterfeit Label:**



**Distributed:** Known to be distributed in Bangladesh

Share Like 1 Tweet 3 Share 11

UL is a global independent safety science company offering expertise across three strategic businesses: Commercial & Industrial, Consumer and UL Ventures. Our breadth, established objectivity and proven history mean we are a symbol of trust, enabling us to help provide peace of mind to all.

[more >](#)

**About UL**

- [History](#)
- [Leadership](#)
- [Careers](#)
- [Corporate Social Responsibility](#)
- [Newsroom](#)

**Information for**

- [Manufacturers](#)
- [Code Authorities](#)
- [Consumers](#)
- [Retailers](#)

**Dashboard**

- [Library](#)
- [Marks Hub](#)
- [Services](#)
- [Standards](#)

**Help**

- [FAQs](#)
- [Locations](#)
- [New to UL](#)

**Resources**

- [MyHome at UL](#)
- [Online Certifications Directory](#)
- [Sustainable Product Guide](#)
- [Certification Marks](#)
- [UL Certification Bodies](#)
- [UL Collaborative Standards Development System](#)
- [Standards Certification Customer Library](#)
- [UL iQ™](#)
- [Request for Quote](#)
- [Report a Concern](#)